

CLEANFLO RESEARCH AND TESTING CENTRE

(A Unit of CLEANFLO INDIA PRIVATE LIMITED)

403, Gupta Tower, Commercial Complex, Ring Road, Azadpur, Delhi-110033 India, Tel.: 91-11-47003700
E-Mail: crclab@cleanflo.com; cleanflo@cleanfloindia.com, Web site: <http://www.cleanflo.com>

An ISO 9001, ISO 14001, OHSAS 45001 Certified Laboratory

QUALITY INSPECTION REPORT

REF. NO.: CRTC-R&D:25-26:0971
DATE : 31.12.2025

ISSUED TO: M/S. ION ROBINSON INDIA
D-2/2, GROUND FLOOR, YADAV NAGAR,
SAMEYPU, DELHI – 110042.

SAMPLE NO.	'12251204
PRODUCT NAME	Anthracite Coal
SAMPLE RECEIVED ON	30.12.2025

SL	PARAMETERS	RESULTS OBTAINED	UNIT
1	Ash Content	5.51	%/mass
2	Fixed Carbon	86.74	%



AUTHORISED SIGNATORY

Doc.: CRTC/QF/7.8/01

Rev.:01

Date:12.01.2024

- The results listed refer only to the tested sample(s) and applicable parameter(s). Endorsement of products is neither inferred nor implied.
- Total liability of our Laboratory is limited to the invoiced amount, if applicable.
- Sample(s) will be destroyed after 30 days from the date of issue of test certificate unless otherwise specified.
- This report is not to be reproduced wholly or in part and cannot be used as evidence in the court of law and should not be used in any advertising media without our special permission in writing.
- In case any reconfirmation of contents of this test certificate is required, please contact our office.



(AN ISO - 9001:2015, 14001:2015 &
OHSAS 45001:2018 CERTIFIED COMPANY)